Work Order Bid (ID)



WORK ORDER INFORMATION

Work Order Name: WO/20002BR-0120/1

Work Order Type: Weatherization

Audit Name: 20002BR-0120AUDIT

CLIENT INFORMATION

Client ID: 20002BR-0120

AGENCY INFORMATION

Agency: Bradley-Cleveland Community Services Agency

Agency Phone: (423) 479-4111

Address: 155 Sixth Street SE **Fax:** (423) 479-4113

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1996 Mobile Home Approx 1005 sqft

Auditor: Darrell Bloodworth Phone: (423) 505-4585 Email: Darblood@comcast.net

Measures

Client ID: 20002BR-0120

	Measure 1 Seal	Ducts			Componen	ts		ı	Inspected
C	comment Supply of	ducts. Airseal to less thar	1.0 pa						
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Duct sealing (setup cost)	Each	1					
10	Miscellaneous Supplies	Duct Sealing	Each	7					
(Other Detail						1		
L									
L									
				Measur	e Sub Total:			Sub Total:	
	Comment Airseal a handler,	eral Air Sealing abandoned return in living Attach and airseal pane e end from water heater)	behind b			ntration a			Inspected
	`	,			Estimated	<u>'</u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	General air sealing (setup cost)	Each	1					
10	Miscellaneous Supplies	Infiltration Reduction	See Above	1					
(Other Detail								
					[1	Sub Total:	
				Measur	e Sub Total:			oub rotui.	

Measure 3 DWI	H Pipe Insulation			Componer	nts			Inspected
Comment				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Pipe Insulation	Linear Foot	5					
	costs to add 10' wrap to hot/cold							
2 Labor	DWH Pipe Insulation	Each	1					
3 Other	DWH Pipe Insulation	Each	1					
Other Detail] [
							Out Take	
			Measur	e Sub Total:			Sub Total:	
	H Tank Insulation			Componer	nts			Inspected
Measure 4 DWI	H Tank Insulation			Componer			Actual	Inspected
	H Tank Insulation Description / Comment	Units	Qty	-		Qty		Inspected Total
Comment		<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Comment # Material / Labor	Description / Comment			Estimated	1	Qty	Actual	
Comment# Material / Labor1 Insulation	Description / Comment DWH Tank Insulation	Each	1	Estimated	1	Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment DWH Tank Insulation	Each	1	Estimated	1	Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment DWH Tank Insulation	Each Each	1 1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DWH Tank Insulation	Each Each	1 1	Estimated	1		Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment DWH Tank Insulation	Each Each	1 1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DWH Tank Insulation	Each Each	1 1	Estimated Unit Cost	1		Actual Unit Cost	

Client ID: 20002BR-0120

Measure 5 Bell	y Cellulose Loose			Componen	ts		•	Inspecte
•	holes in belly wrap 2 @ 4 ements.	4'x4', 3 @ 2	2'x2', a	nd 1 @ 1'x3'	. Approx			
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Celluls,Blwn	Bag	50					
2 Labor	Floor Insulation - Celluls,Blwn	Bag	50					
3 Other	Floor Insulation - Celluls,Blwn	Each	1					
Miscellaneous Supplies	Added Misc Cost	Each	1					
Other Detail								
			Moasur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 6 Fix	Improper Venting (Clot	hes Dryer)	Componen	ts		1	Inspecte
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	Equipment	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
			Measur	re Sub Total:		,	Sub Total:	
Field Notes:			Measur	re Sub Total:		,	Sub Total:	
Field Notes:			Measur	e Sub Total:		,	Sub Total:	
Field Notes:			Measur	re Sub Total:			Sub Total:	

Client ID: 20002BR-0120

Measure 7 Install Bathroom Exhaust Fan			Components			Inspected			
C	comment Vent Un	it to the Exterior							
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Bathroom exhaust fan	Each	2					
2	Labor	Labor	Each	2					
C	Other Detail								
									-
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								
L									
			Work Or	der Gra	nd Total:		Gran	d Total:	